



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
January 30, 2007

Supervisor DRZ

Mine Name: Topaz Valley Limestone
Operator Name: Rancho Equipment Services
1557 W. Ashby Road
Delta, Utah 84624-7357
Inspector(s): Tom Munson
Other Participants: None
Mine Status: Reclaimed

Permit number: M0230022
Inspection Date: 05/09/2006
Time: 11 AM

Weather: Sunny

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection: To see if the vegetation and other reclamation parameters had been meet.

Directions to Site: Northwest of Delta on the Brush Wellman Road

Inspection Summary: The inspection revealed that the vegetation (four wing, forage koshia, and some wheat grass) had become established over five years and multiple seedings. The minor amount of erosion observed was not significant enough to be concerned about it affecting stability of the reclamation. Overall the site had improved significantly from previous years that suffered from over fertilization.

Conclusions and Recommendations:

It was concluded by the inspector that the site and the bond should be released by the Division.


Inspector's Signature Thomas Munson **Date:** 2/27/07

DH:tm:pb

cc: Operator
BLM, Fillmore

Attachment: Photos

M0230022



MINOR EROSION



FORAGE HOSHA



M0230022

